



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 21, 2008

Reviewed SW

| | |
|------------------------------------------|--------------------------------------|
| Mine Name: Strawberry River | Permit Number: S0130008 |
| Operator Name: Rock & Stone LLC | Inspection Date: May 21, 2008 |
| Inspector(s): L Heppler | Time: 10:00 am |
| Other Participants: Marty Appawoo | Mine Status: Act |

| Elements of Inspection | Evaluated | Comment | Enforcement |
|-----------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Concurrent Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Bond Renewal Date: 04-15-2010

Purpose of Inspection: This was a routine annual inspection

Inspection Summary: Mine was in full operation with several Excavators and Loaders working. Several highwall areas had unsupported overhangs that are a safety hazard. Large area south of the road was being used as a waste rock site (topsoil was stockpiled), but area was clearly outside of permitted area.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator has to comply with all local, state and federal rules. Operator has 10 days to file an interim bond to cover additional disturbed area (2.29 acres – \$11,900) see attached map. Operator has 90 days to file for a Large Mine Permit with DOGM. Interim bond will be adjusted after large Mine permit is completed. Failure to comply will result in a Cessation order. DOGM Assessment Officer has been notified of Inspection Report. Disturbed area south of road was photographed and GPS taken. Continue to monitor this site when in the area.

Inspector's Signature

[Signature]

LAH:pb

cc: Cliff Read- Rock & Stone

Fee

O:\WP\M013-Duchesne\S0130008-Strawberry\Draft\Insp_StrwberryRiver_05-21-08.doc

cc: *okuniewicz.michael@dol.gov*

Inspection Date: May 21, 2008
Page 2 of 2
S/013/0008

Photos Taken 05-21-08





Mine Number: S130008

Name: STRAWBERRY RIVER

Township 04.0 S Range 07.0 W Section 16

Meridian: SLBM

Inspection Date: 20/08/5/21

Map Produced by DKS

| | |
|----------------------|------|
| Acres Disturbed | 6.09 |
| Acres Regraded | 0 |
| Acres Seeded | 0 |
| Road Acres Disturbed | 0.40 |


| | |
|-----------------------|------|
| Total Acres Disturbed | 6.49 |
|-----------------------|------|

| | |
|-------------------|------|
| Acres Released | 0.19 |
| Acres Excluded | 0 |
| Acres PreExisting | 0 |
| Acres Prelaw | 0 |

symbolized in legend may not be appear on map

| | | |
|-------------|-----------------------------------------------|-------------------------|
| Mines | — Township or range Line | Disturbed |
| Open Mines | --- Township or range line: location doubtful | Regraded |
| Open Status | — Section line | Seeded |
| Boundary | --- Section line: location doubtful | Released |
| Access | — Access | Excluded |
| Route | — Mine | PreExisting |
| Route | — NonMine | Prelaw |
| Route | — Reclaimed | Proposed |
| Route | — Other | Bond Area |
| Route | | SITLA Mineral Leases |
| Route | | BLM Salable Minerals |
| Route | | BLM Mining Notices |
| Route | | Community Pit |
| Route | | SITLA Mineral Ownership |

NAIP imagery date 2006



0 625

Feet

1:7,500 1 inch equals 625 feet

Verify Scale

Natural Resources
of Oil, Gas, and Mining
Lines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.

6/4/2008 NAD 1927 UTM Zone 12N

526400 526800 527200 527600 528000 528400

528400

8

9

10

16

15

20

21

22

526400 526800 527200 527600 528000 528400

4441600 4442000 4442400 4442800 4443200

Mine Number: S130008

Mine Name: STRAWBERRY RIVER

Township 04.0 S Range 07.0 W Section 16

Meridian: SLBM


Inspection Date: 20/08/5/21
Map Produced by DKS

| | |
|-----------------------|------|
| Acres Disturbed | 6.09 |
| Acres Regraded | 0 |
| Acres Seeded | 0 |
| Road Acres Disturbed | 0.40 |
| Total Acres Disturbed | 6.49 |
| Acres Released | 0.19 |
| Acres Excluded | 0 |
| Acres PreExisting | 0 |
| Acres Prelaw | 0 |

Legend
All items symbolized in legend may not be appear on map

- Active Mines
- Inactive Mines
- Unknown Status
- County Boundary
- Interstate
- US Route
- State Route
- Primary Route
- Secondary Route
- Main Dirt Road
- Unimproved Road
- Interchange
- Trail
- Disturbed
- Regraded
- Seeded
- Released
- Excluded
- PreExisting
- Prelaw
- Proposed
- Bond Area
- SITLAMineral Leases
- BLM Salable Minerals
- BLM Mining Notices
- Community/Pit
- SITLAMineral Ownership

NAP imagery date 2006



0 625
Feet

1:7,500 1 inch equals 625 feet
Verify Scale

Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program
6/4/2008 NAD 1927 UTM Zone 12N
Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.